

**Kansas City**

15700 College Blvd. Ste 201
 Lenexa, KS 66219
 Telephone: (913) 307-4500
 Fax: (913) 307-4598

CRM: Josh Wallace
Phone #: (913) 307-4514
Fax #: (913) 307-4595
Email: Josh.Wallace@Pulte.com

Service Request # KC17196

Request Date 11/17/2006

LOT INFORMATION

Community	Reserve - The Villas	Lot Address	8712 Quill St. Lenexa, KS 66227	Close Date	08/18/2006
Lot/Block	17400			Plan / #	2182 Brampton / 02182
Building #				Phase #	

CONTACT INFORMATION

Name	Cynthia Daugherty	Primary Phone	(913) 745-5103 (Home)	Other Phone	(913) 966-7355 x (Her Mobile)
Email					

SERVICE REQUEST INFORMATION

Source	Pulte Initiated Contact	Type	3 Month Follow Up	Status	In Progress
Notes					

LINE ITEM INFORMATION

L/I #	Parent #	W/O #	Issue	Status	Inspection Appt	Service Appt
1	NA		Grading >> Exterior >> Sink Holes :	In Progress		
Additional Description: SPRING 2007 - STEP #2: Repair settlement area near front mulch bed and depression near curb and neighboring driveway. Additional areas may need repair, however, we will first need to shoot the grade as per item #2. (review 4/1/07)						
Assigned To: GORDON ENERGY & DRAIN			Initials:			
2	NA		Grading >> Exterior >> Draining Improperly :	In Progress		
Additional Description: SPRING 2007 - STEP #1: Reinspect and evaluate homeowner's concerns of poor drainage / standing water along the entire rear property line and front yard areas noted in item #1. Elevation shots will be taken to determine where challenge areas exist. Upon completion of this evaluation, any warrantable repairs will be determined at that time. (review 4/1/07)						
Assigned To: HOUSEWORX, INC.			Initials:			

Yes No

 Was your warranty request resolved in a timely manner? Was your home left clean after the warranty work was complete?

The items have been completed to my satisfaction.

Homeowner_____
Date_____
Pulte Representative_____
Date